## Identified Transportation Issues

Data Collection

Field Observations

Public Inputs





## Summary of Transportation Issues Identified Along the Military Road/Missouri Avenue Corridor

- Excessive speeds along the corridor identified by community stakeholders were confirmed
- Posted speed limit increases in Rock Creek Park, contributing to exceeding lower speed limits on either side of the park
- Speed limit signs are sometimes obscured
- Congestion occurs at several key intersections
- Pedestrian activity is evident at some of the intersections





## Summary of Transportation Issues Identified Along the Military Road/Missouri Avenue Corridor -- continued

- High accident rates at many intersections
- Poor pavement markings along most corridor segments
- Parking limits should be clearly defined
- Heavy trucks constitute between 2 and 5% along the corridor of traffic.
- Light truck traffic (two-axle, 4-tires), including vans and pickups constituted between 5 and 18%.
- Eastbound movement of light trucks heavier than westbound movement along the corridor.



